

## M.C Fouz

CMS Week, March 2002

# **Chamber construction Status**

	COMF	PLETED			
	CERN	CIEMAT	SLs Tested	SLs Mechanically assembled	SLs Being assembled
CHAMBER Serial Number	#1 #2 #3 #4	#6 #7 #8	#9	#10	#11

Next Shipment to CERN:

Chambers #6,#7,#8,#9,#10\_\_\_\_ ~10 April





In several SLs the O-ring used was not the correct one



Chamber	SL		Time Co	nstant		
		Madrid	ISR1	ISR2	ISR3	Comments
	P1	125		250		
3	Ζ	277	6.2	166		
	P2	635		93		Probably chamber handling problem
	P1	40		38		
4	Ζ	50	6.1	61		
	P2	25		20	91	After changing O-ring HV Side
	P1	20		18	592	After changing O-ring FE Side
5	Ζ	50	34.8	64		
	P2	70		8*	192	After changing O-ring FE Side

ISR1 => Gerd Fetchenhauer ISR2 => Jesús Puerta (J.P.) ISR3 => J.P. after some improvements

(\*) Due to gas connector

**Dead Channels** 



4 Dead Channels < 1%

Most of HV dead cells due to Sparking Strips.

NO FE dead channels for the last 4 chambers.

The FE problems were mainly due to:

#### Dead Channels on the blue connector

Now we test them and on the last group the failure rate is 0%

Some dead channels on the FE boards

Now we have enough FE Boards to replace the bad ones









BUT

After switching OFF the HV noisy channels are still noisy

By taking out the HV System the noise disappears



#### Switching off the HV



But the noise change from run to run

This kind of noise appears mainly on channels on the 2 first and 2 last FEBs



### The noise affects the timebox shape

#### Taking out the HV system

1

NO HV SYS

1

0.8

0.6

0.4

0.2

0



Time needed for equipping with electronics and testing

From January 14th to March 3th => 3 chambers were equipped with HV and FE electronics, and were tested

Chamber #7:3 weeksChamber #8:2 weeksChamber #9:2 weeks

(It includes some extra work during weekends )

Hardware for tests available at CIEMAT

