


**RO-MC production**  
**ROS-25 status**  
**40 MHz patterns**

---

# RO MINICRATE PRODUCTION STATUS <sup>2</sup>




- Up to 212 MCs have already been delivered to Legnaro, 85% of the production is finished.
- Production of 250 MCs will be finished by february:
  - ▶ 17 MCs will be delivered as soon as possible in january.
  - ▶ 22 MCs will be delivered by beginning of february.
- Afterwards, the spares will be assembled (between 14 – 19 MCs spares, according to the availability of parts).



# ROS-25 STATUS

- The part needed to test the interface with the DDU is already finished.  
The tests could start as soon as Torino is ready.
- For the full ROS-25, we had a problem with one of the piggy boards and we had to produce the PCB again.
- New PCB is now at CIEMAT and we are finishing the tests.
- Hopefully, by the end of next week we could deliver to Legnaro:



- 1 ROS-25.
- 1 TIM board.
- 1 Sector Collector crate.



# 40 MHz patterns

# Modulation of the time measurement by the ROB clock.





RO-MC (no TRBs) working at LHC clock, and ROB 1 with an external 38,52MHz clock.




## Conclusion:

The modulation present at the time measurements ( $\pm 10\%$ ) is due to the clock at each ROB (no influence of the MC clock).


# Time boxes of different channels with and without TRB



# Cases B and C: Double hit detected.



Looking at the data in detail, you can see that sometimes there are two hits that cannot come from the pulse generator.




Time difference = width of the pulse (~63 counts, 50 ns)


```

ROB HEADER
TDC 1 Ch 31 Time 788
ROB TRAILER
ROB HEADER
ROB TRAILER
ROB HEADER
TDC 1 Ch 31 Time 941
TDC 1 Ch 31 Time 1004
ROB TRAILER
ROB HEADER
TDC 1 Ch 31 Time 486
TDC 1 Ch 31 Time 549
ROB TRAILER






```



**We are detecting the falling edge as rising edge.**  
**In some channels it always happens (case C) but in others it only happens depending on the clock phase with respect to the hit (case B).**



# Cases B and C: Double hit detected.




Each TDC has a programmable deadtime (common to all channels). (Values ~5ns, 10ns, 30ns, 100ns).

With this, the second hit could be eliminated.




# Cases D: No double hit detected.






In this case, there is no double hit, the influence is directly on the rising edge of the hit.

The hit has a window of  $\sim 2\text{ns}$  where the TDC can detect it anywhere. In this region, the signal is much more sensible to any clock influence. This influence happens in a window of  $\sim 2\text{ ns}$ , so the effect should not be much worst than that.




Some examples:



## Dependence with channels

- Some ROB channels are more sensible to this kind of effects.
- Actually, all of the channels found with this problem belong to groups of channels going to two different BTIMs.
  - Sensible channels:
    - Channels 0 to 4 of all TDCs.
    - Channels 27 to 31 of all TDCs.
- Specially bad ones are channel 4 and channel 27 of all TDCs.



- In our setup, phase modulation is entirely happening inside ROB, compatible with TDC specs.
- Double pulse detection can be solved by:
  - Setting TDC dead time to 100 ns.
  - Setting MAD pulse width  $< 100\text{ns}$ .
- Leading edge interference with TRB ( $< 2\text{ns}$ ) can not be solved.

## Next steps

- Evaluate possible phase modulation at LVDS inputs.
- Characterize leading edge problem channel by channel.