

AoB

Additional Items for SX/UX

Mu Barrel Technical Board
CMS week June 20th 2006

A. Benvenuti
INFN Bologna

- MB4 protection for Sectors 2, 3, 4, 5, 6

The chambers are exposed to items falling down from the walkways and to people stepping on them. Foot prints are visible on YB0+ S03.

- MB1 protections Sectors 8, 9, 10, 11, 12, same reasons as for MB4 but needed only with detector open
- Tool to extract chambers for servicing in situ (Theta SL).

This could be feasible for Sectors 3,4,5 and 9, 10, 11 with simple rails attached between the wheels. For YB+2 could extract from HV side.

- Power tool to move chambers along the rails(~20cm)